



Public Works Monthly Report


August 2021

Statistics at a Glance


Surface Water Pumped – 330.5 MG

Work Orders – 1,769

Surface Water Pumped



Work Orders and Inspections



Note: Work orders are possible repairs on equipment or lines, potholes, street signs, traffic signals, etc. that have been initiated by customers or staff. Totals include FOG Inspections, Public Works Inspections, approved Backflow Test Reports, Locates, Service Requests, and previous work orders that were entered for inspections that the department has now started tracking through Cityworks.