

Public Works Monthly Report

November 2020


Statistics at a Glance

Surface Water Pumped – 176.8 MG


*October 2020 has been corrected

Work Orders – 1,269

Surface Water Pumped



Work Orders and Inspections



Note: Work orders are possible repairs on equipment or lines, potholes, street signs, traffic signals, etc. that have been initiated by customers or staff. Totals include FOG Inspections, Public Works Inspections, approved Backflow Test Reports, Locates, Service Requests, and previous work orders that were entered for inspections that the department has now started tracking through Cityworks.